Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261105131439
Test Time: 2026-11-05 13:14:39
Technician: --

2020 (L) Skoda VEHICLE DIAGNOSTIC REPORT

Vehicle Information

2020 (L)/Skoda/Octavia 2013 >/Motors
VIN: TMBJU7NE2L0014301

Odometer Reading: 144523km
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MX808
Version: V25.00

Serial Number: DR7GM9C01740
Repair Order Number: --

System Scanned (28)

System	Status/DTC
01 - Engine Control Module 1	2
02 - Transmission electronics	0
03 - Brakes 1	1
08 - Air conditioning	2
09 - Electronic central electric	4
13 - Adaptive cruise control	2
14 - Wheel Damping Electronics	0
15 - Airbag	0
17 - Instrument cluster	0
19 - Gateway	1
2B - Steering Column Locking	0
32 - Lock Electronics	0
3C - Lane change assistance	0
42 - Driver's door electronics	1
44 - Power steering	0
47 - Sound system	0
4B - Multi-function module	0
52 - Passenger's door electronics	0
5F - Information electronics 1	1
6C - Rear view camera system	0

6D - Rear lid electronics	0
75 - Telematics Communication Unit	0
76 - Parking aid	0
A5 - Front sensor for driver assistance systems	0
A9 - Structure-Borne Sound Actuator	0
B7 - Interface for access/start system	2
D6 - Light control left 2	0
D7 - Light control right 2	0

DTC (16)

01 - Engine Control Module 1 (2 DTCs)

DTC	Description	Status
U112300	Databus error value received	Passive/Sporadic
P056800	Cruise Control System (CCS) switch ,Range/performance	Passive/Sporadic

03 - Brakes 1 (1 DTC)

DTC	Description	Status
C102D00	Tire pressure warning	Active/static

08 - Air conditioning (2 DTCs)

DTC	Description	Status
B109811	Defroster flap motor position sensor ,Circuit short to ground	Passive/Sporadic
B10CD00	Function restriction caused by energy management	Passive/Sporadic

09 - Electronic central electric (4 DTCs)

DTC	Description	Status
B147A18	Remote control vehicle key 2 ,Insufficient current	Passive/Sporadic
B147A54	Remote control key 2 ,No basic setting	Passive/Sporadic
B147B18	Remote control vehicle key 3 ,Insufficient current	Active/static
B105D01	Steering column electronic systems control module , Electrical malfunction	Passive/Sporadic

13 - Adaptive cruise control (2 DTCs)

DTC	Description	Status
U112300	Databus error value received	Passive/Sporadic
U112200	Data bus message implausible	Passive/Sporadic

19 - Gateway (1 DTC)

DTC	Description	Status

B1802F1	NV-Energy management ,Alarm triggered	Passive/Sporadic

42 - Driver's door electronics (1 DTC)

DTC	Description	Status
B122D29	Locking unit for central locking ,Range/performance	Active/static

5F - Information electronics 1 (1 DTC)

DTC	Description	Status
B1297F2	Multimedia system display unit 1 ,Above upper temperature limit	Passive/Sporadic

B7 - Interface for access/start system (2 DTCs)

DTC	Description	Status
U140000	Function restriction ,due to low voltage	Passive/Sporadic
U112200	Data bus message implausible	Passive/Sporadic

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.